



APM

MARYVILLE, VICTORIA



smoke containment screens • smoke curtains • fire curtains • horizontal fire curtains • smoke & heat release vents • natural ventilation • fire resistant glazing • horizontal glazing • smoke doors • fire doors • intumescent paint & other specialty systems

Problem

Fire separation was required in a warehouse that was located in an area of high traffic movement.

Solution

Smoke Control installed Fibershield Fire Curtains to the areas that required fire compartmentation.

Design Considerations

The system installed was required to be compact and have the ability to operate in conjunction with a high speed door. In addition the system had to provide a 2 hour fire rating.

Client

Australia Door Systems

*Note: Each project is unique and usually requires the involvement of a Fire Safety Engineer.
Please contact us to discuss the suitability of this solution for your project.*





IVY 330

GEORGE ST, SYDNEY



smoke containment screens • smoke curtains • fire curtains • horizontal fire curtains • smoke & heat release vents • natural ventilation • fire resistant glazing • horizontal glazing • smoke doors • fire doors • intumescent paint & other specialty systems

Problem

Basement loading dock joining two buildings.

Solution

Installation of a 12m wide x 3.5m height Fibershield 4 fire curtain.

Design Considerations

The system required a 4 hours (-/240/-) fire rating. A 4 hour Maxilite fire rated bulkhead was installed above the curtain.

Client

Lucas Stuart Pty Ltd

Fire Safety Engineer

DeFire

*Note: Each project is unique and usually requires the involvement of a Fire Safety Engineer.
Please contact us to discuss the suitability of this solution for your project.*

